

AREA	WALL COVERING TYPE	FLOOR COVERING	CODE DEFICIENCY	COMMENTS
Foyer	PAINT	TILE	NO	N/A
Lobby	WALLPAPER	TILE/CARPET	NO	N/A
Front Desk	WALLPAPER	CARPET	NO	N/A
Laundry	PAINT	TILE	NO	N/A
Back of House	PAINT	TILE	NO	N/A
Market/Sundries	WALLPAPER	TILE	NO	N/A
Storage	PAINT	TILE	NO	N/A
Lobby Restroom - Men	WALLPAPER	TILE	NO	N/A
Lobby Restroom - Women	WALLPAPER	TILE	NO	N/A
Office - General Manager	WALLPAPER	CARPET	NO	N/A
Business Center	WALLPAPER	CARPET	NO	N/A
Stairwell - East	WALLPAPER	TILE	NO	N/A
Stairwell - West	WALLPAPER	TILE	NO	N/A
IT Room	N/A	N/A	N/A	ACCESS NOT PROVIDED
Elevator	STEEL	WOOD	NO	N/A
Guest Laundry	WALLPAPER	TILE	NO	N/A
Fitness Room	WALLPAPER	TILE	YES	ADDITION - UNPERMITTED WORK
Mechanical Room - 1st Floor	UNFINISHED DRYWALL	CONCRETE	NO	N/A
Electrical Closet	PAINT	TILE	NO	N/A
Closet - 2	PAINT	TILE	NO	N/A
Closet - 3	PAINT	TILE	NO	N/A

UNIT NO.	ROOM TYPE	ROOM STATUS	BATHROOM STATUS	WALL COVERING TYPE	CODE DEFICIENCY	COMMENTS
101	UGI	INTACT W/ FURNITURE	INTACT	PAINT ONLY	NO	N/A
102	KING	INTACT W/ FURNITURE	INTACT	PAINT ONLY	NO	N/A
103	UGI	INTACT W/ FURNITURE	INTACT	PAINT ONLY	NO	N/A
104	KING	INTACT W/ FURNITURE	INTACT	PAINT ONLY	NO	N/A
105	DD	INTACT W/ FURNITURE	INTACT	PAINT ONLY	NO	N/A
106	KING	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
107	DD	INTACT W/ FURNITURE	INTACT	PAINT ONLY	YES - SEE COMMENT	WINDOW - CRACKED
108	KING	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
109	DD	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
111	KING	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
121	ADA KING	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	YES - SEE COMMENT	MISSING DRYWALL
122	KING	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
123	DD	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
124	KING	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
125	DD	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	YES - SEE COMMENT	MISSING DRYWALL
126	KING	INTACT W/ FURNITURE	INTACT	PAINT ONLY	NO	N/A
127	ADA DD	INTACT W/O FURNITURE	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
128	ADA KING	INTACT W/ FURNITURE	INTACT	PAINT ONLY	NO	N/A
129	DD	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
130	DD	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A

UNIT NO.	ROOM TYPE	ROOM STATUS	BATHROOM STATUS	WALL COVERING TYPE	CODE DEFICIENCY	COMMENTS
201	KING SUITE	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
202	DD	INTACT W/ FURNITURE	INTACT	WP + TX	YES - SEE COMMENT	MISSING DRYWALL
203	KING SUITE	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
204	DD	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A
205	DD	DEMOLISHED	PARTIALLY DEMO'D	WALLPAPER	NO	N/A
206	KING	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
207	DD	DEMOLISHED	PARTIALLY DEMO'D	WALLPAPER	NO	N/A
208	KING	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
209	DD	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
210	KING	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
211	KING	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	YES - SEE COMMENT	MISSING DRYWALL
212	KING	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
213	KING SUITE	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
214	KING	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
215	KING SUITE	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
216	DD	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
217	KING SUITE	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A
218	DD	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
219	KING SUITE	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A
220	DD	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
221	ADA KING	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
222	KING	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
223	DD	DEMOLISHED	PARTIALLY DEMO'D	TEXTURE	NO	N/A
224	KING	DEMOLISHED	PARTIALLY DEMO'D	WP + TX	NO	N/A
225	DD	DEMOLISHED	PARTIALLY DEMO'D	TEXTURE	YES - SEE COMMENT	MISSING DRYWALL
226	KING	DEMOLISHED	PARTIALLY DEMO'D	PAINT ONLY	NO	N/A
227	KING SUITE	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A
228	DD	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
229	KING SUITE	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
230	DD	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A

INTACT = NO WORK TO DATE

UGI - DOUBLE WITH COUCH

DD - DOUBLE NO COUCH

KING - KING NO COUCH

KING SUITE - KING WITH COUCH

UNIT NO.	ROOM TYPE	ROOM STATUS	BATHROOM STATUS	WALL COVERING TYPE	CODE DEFICIENCY	COMMENTS
301	KING SUITE	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
302	DD	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
303	KING SUITE	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
304	DD	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
305	DD	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
306	KING	DEMOLISHED	PARTIALLY DEMO'D	WALLPAPER	NO	N/A
307	DD	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
308	KING	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
309	DD	DEMOLISHED	PARTIALLY DEMO'D	WALLPAPER	NO	N/A
310	KING	DEMOLISHED	PARTIALLY DEMO'D	WALLPAPER	NO	N/A
311	KING SUITE	DEMOLISHED	PARTIALLY DEMO'D	WALLPAPER	NO	N/A
312	KING SUITE	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
313	KING SUITE	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
314	KING	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
315	KING SUITE	INTACT W/ FURNITURE	INTACT	WALLPAPER	NO	N/A
316	DD	INTACT W/ FURNITURE	INTACT	WALLPAPER	NO	N/A
317	KING SUITE	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A
318	DD	INTACT W/ FURNITURE	INTACT	WALLPAPER	NO	N/A
319	KING SUITE	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A
320	DD	INTACT W/ FURNITURE	INTACT	WALLPAPER	NO	N/A
321	ADA KING	DEMOLISHED	PARTIALLY DEMO'D	WALLPAPER	NO	N/A
322	KING	INTACT W/O FURNITURE	INTACT	WP + TX	NO	N/A
323	DD	DEMOLISHED	PARTIALLY DEMO'D	WALLPAPER	NO	N/A
324	KING	INTACT W/ FURNITURE	INTACT	WALLPAPER	NO	N/A
325	DD	DEMOLISHED	PARTIALLY DEMO'D	TEXTURE	YES - SEE COMMENT	MISSING DRYWALL
326	KING	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A
327	ADA DD	INTACT W/ FURNITURE	INTACT	WP + TX	NO	N/A
328	DD	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A
329	KING SUITE	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A
330	DD	INTACT W/ FURNITURE	INTACT	TEXTURE	NO	N/A

INTACT = NO WORK TO DATE

UGI - DOUBLE WITH COUCH

DD - DOUBLE NO COUCH

KING - KING NO COUCH

KING SUITE - KING WITH COUCH